

United States Steel Corporation Clainton Works 400 State Street Clainton, PA 15025

RECEIVED

March 31, 2002

OFFICE OF RESIDENCE ARRESTMON

APR - 4 2002

Mr. Donald S. Welsh Regional Administrator U.S. EPA Region III 1650 Arch Street Philadelphia, PA 19013

Dear Sir:

Subject: NESHAP Benzene Waste Operations

40 CFR Part 61 - Subpart FF - 2001 TAB

In accordance with requirements of the Benzene Waste NESHAPS Subpart FF, USS Clairton Works is submitting annual benzene waste stream information for our coke by-product recovery facility.


Please find attached the annual report that identifies benzene waste streams and the corresponding Total Annual Benzene (TAB) quantities for 2001. USS is also in compliance with the recordkeeping requirements of 40 CFR 61.356.

If you have any questions, our technical contact, R. P. Spargal, P.E., can be reached at (412) 233-1486.

Sincerely,
Raymonl'RJOGS

Raymond R. Terza General Manager

USS Clairton Works





Points of Generation/Waste
Types and Analyses Methods

Sludge/Wastewater Sources

Mtce. – Pumps Drainage

Mtce. – Pump Seals Leakage

Mtce. – Vessel Drainage

Mtce. – Exchanger Drainage

Mtce. – Valves Drainage

Mtce. – Instrumentation

Process Sampling

Process Unit Turnarounds

2001 TAB -Total Annual Benzene Report